TROPICAL ATMOSPHERE-OCEAN (TAO) PROGRAM FINAL CRUISE REPORT

RB-14-06

Area: Equatorial Pacific: 8°S 155°W to 8°N 155°W

Itinerary:

RB-14-06 DEP November 5, Kwajalein Atoll, RMI

ARR November 24, 2014, Honolulu, HI

CRUISE DESCRIPTION

The Tropical Atmosphere Ocean (TAO) array consists of 70 buoys utilizing a taut line mooring configuration used to mount data collection sensors for climate research purposes. Fifteen buoys are serviced by JAMSTEC and the remaining 55 buoys from 95°W longitude to 165°E longitude are serviced by National Data Buoy Center (NDBC). Repair and maintenance of the buoys is performed by NDBC contracted personnel on an annual basis utilizing the NOAA Ships and other contract vessels. The buoys' deployment lifecycles are up to 18 months to ensure at least one year of data collection can be completed.

NDBC Points of Contact

NDBC Operations Branch Chief NDBC Operations Manager

Steve Cucullu Jeff Jenner

National Data Buoy Center National Data Buoy Center

Building 3205 Building 3205

Stennis Space Center, MS 39529 Stennis Space Center, MS 39529

228-688-3804 228-688-2784

Email: stephen.cucullu@noaa.gov
Email: jeff.jenner@noaa.gov

TAO Cruise Objective and Plan:

The objective of this cruise was the maintenance of the TAO Array along the 155°W meridian.

The scientific complement for the cruise embarked at Kwajalein, Atoll, RMI on November 4, 2014. The

ship departed on November 5, 2014 and conducted operations as listed in Section 2.1. The ship arrived at Honolulu, HI on November 24, 2014.

1.0 **PERSONNEL**

1.1 <u>CRUISE LEAD AND PARTICIPATING SCIENTISTS</u>:

Cruise Lead: James Rauch.

Participating Scientists:

Name	Gender	Nationality	Affiliation
James Rauch	M	US	NOAA/NDBC
James Haden	M	US	NOAA/NDBC
Stephan Becerra	M	US	NOAA/NDBC

2.0 **OPERATIONS**

2.1 TAO Data Recovery Summary

Mooring Operations conducted are shown in the tables below. The following provides details on the data recovery efforts for the buoys serviced. All noted times in this summary report are Coordinated Universal Time (UTC):

Cruise Summary

Buoy Site: 0 180			
Mooring Operation: Visit	Mooring ID#: DM079A		
Deployed Location: 00 01.785N 179 55.191W	Deployed Date: 07/27/14		
Current Location: 00 01.847N 179 53.548W Visit Date: 11/08/14			
Sensors/Equipment Lost at Sea: None			
Sensors Damaged/Fouled: None			
Fishing/Vandalism: None			
Sensors/Tubes Downloaded: None			
General Comments: Unplanned visit conducted due to buoy proximity to the track line.			

Buoy Site: 8S 170W	
Mooring Operation: Recovery	Mooring ID#: DM043A
Deployed Location: 08 00.53S 170 02.3W	Deployed Date: 06/05/12

Recovered Location: 08 06.5S 170 08.6W **Recovered Date:** 11/10/14

Sensors/Equipment Lost at Sea: None

Sensors Damaged/Fouled: SSC Fouled; Anemometer stanchion failed and was laid over on the tower ring; T25 all clamp screws were stripped and the sensor was damaged while removing the clamps.

Fishing/Vandalism: Fishing line was on bridle down to the first sensor. Rope was tied off to bridle as well. Buoy off station.

Sensors/Tubes Downloaded: None

General Comments: Recovery added to mission after the previous cruise had a ship casualty preventing the recovery. Mooring broke from anchor, directly under the release. The acoustic release had no comms and appeared to have been dragged in the mud on the ocean floor. The release link was still attached to the release but no shackles nor chain.

Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service
			Observations
Buoy	7/12/14	No transmits	None
ATMP	7/10/14	Data missing	None
T25	4/20/14	Data missing	Damaged, fishing gear
T50-T125	4/20/14	Data missing	None
T150	4/20/14	Data missing	No comms, mount slid
T200	4/20/14	Data missing	Mount slid
T250-T500	4/20/14	Data missing	None
RH	6/11/13	Data too high	None
Wind	8/23/12	WDIR erratic	Upper stanchion failure,
			hanging my cable
SSC	6/22/12	Data too low	Fouled, fishing gear

Buoy Site: 8S 155W				
Mooring Operation: Recovery		Mooring ID#: DM(Mooring ID#: DM059A	
Deployed Location: 08 15.32S 155 01.11W		Deployed Date: 10/	Deployed Date: 10/03/13	
Recovered Location: 10 23.58S 160 41.03W		Recovered Date: 11	Recovered Date: 11/12/14	
Sensors/Equipment Lost at Sea: Acoustic Release				
Sensors Damaged/Fouled: SSC, T25 Fouled				
Fishing/Vandalism: None				
Sensors/Tubes Downloaded: None				
General Comments: Buoy adrift.				
Site Sensor Failures Date Data Flagged Why Data Flagged Field Service				
			Observations	
Buoy	12/15/13	Adrift	Outside data grid	

Buoy Site: 8S 155W	Mooring Depth: 5345m	
Mooring Operation: Deployment	Mooring ID#: DM107A	
Deployed Location: 08 17.42S 155 02.41W	Deployed Date: 11/14/2014	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		

Sensors Damaged During Deployment: None
General Comments: None

Buoy Site: 5S 155W				
Mooring Operation: Recovery Mooring ID#: DM060A		[060A		
Deployed Location: 04 58.66S 154 59.55W		Deployed Date: 10	Deployed Date: 10/04/13	
Recovered Location: 04 58.76S 154 59.22W		Recovered Date: 1	Recovered Date: 11/15/14	
Sensors/Equipment L	ost at Sea: None	·		
Sensors Damaged/Fouled: SSC Fouled				
Fishing/Vandalism: Long line gear on T250, TP300				
Sensors/Tubes Downloaded: None				
General Comments: Standard recovery				
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service	
			Observations	
ATMP	12/16/13	Data too low	None	
RH	11/21/13	Data stuck	None	

Buoy Site: 5S 155W	Mooring Depth: 5023m	
Mooring Operation: Deployment	Mooring ID#: DM108A	
Deployed Location: 05 00.02S 154 59.07W	Deployed Date: 11/16/2014	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Standard deployment		

Buoy Site: 2S 155W				
Mooring Operation: Recovery		Mooring ID#: DM	Mooring ID#: DM058A	
Deployed Location: 01 59.15S 154 59.63W		Deployed Date: 10	Deployed Date: 10/01/13	
Recovered Location: 01 58.9S 154 58.6W		Recovered Date: 1	Recovered Date: 11/16/14	
Sensors/Equipment L	ost at Sea: None			
Sensors Damaged/Fou	Sensors Damaged/Fouled: T150-TP500 fouled with fishing gear			
Fishing/Vandalism: Excessive long line gear on mooring				
Sensors/Tubes Downloaded: None				
General Comments: Recovery of low profile buoy				
Site Sensor Failures	Site Sensor Failures Date Data Flagged Why Data Flagged Field Service			
			Observations	
Buoy	5/1/14	Transmit failure	None	
T250	3/8/14	Data missing	No comms	
SST/SSS	1/27/14	Data missing	None	

Buoy Site: 2S 155W	Mooring Depth: 4987m	
Mooring Operation: Deployment	Mooring ID#: DM109A	
Deployed Location: 01 58.4S 155 00.9W	Deployed Date: 11/17/2014	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Standard deployment		

Buoy Site: 0 155W				
Mooring Operation: Recovery		Mooring ID#: DM	Mooring ID#: DM061A	
Deployed Location: 00 00.05N 154 56.90W		Deployed Date: 10.	/05/13	
Recovered Location: 00 00.02N 154 54.78W		Recovered Date: 1	Recovered Date: 11/17/14	
Sensors/Equipment L	ost at Sea: None			
Sensors Damaged/Fou	iled: SSC unplugged, Tl	P500 slid to end of Nilsp	oin (700m)	
Fishing/Vandalism:	None			
Sensors/Tubes Downlo	Sensors/Tubes Downloaded: None			
General Comments: S	Standard CO2 recovery.	CO2 equilibrator bent		
Site Sensor Failures	Date Data Flagged	Why Data Flagged Field Service		
			Observations	
T25-T250	10/30/14	Data missing	None	
TP300	10/10/14	Data missing	None	
Wind	4/17/14	WSPD = 0	None	
SST/SSS	4/15/14	Data missing	No comms/unplugged	
TP500	4/10/14	Data failed	Mount slid	
RH	12/18/13	Data too high	None	

Buoy Site: 0 155W/CO2	Mooring Depth: 4627m	
Mooring Operation: Deployment	Mooring ID#: DM110A	
Deployed Location: 00 00.20N 154 55.16W	Deployed Date: 11/18/2014	
Pre-Deployment On Deck Instrument Failures: None		
Sensors/Equipment Lost at Sea: None		
Sensors Damaged During Deployment: None		
General Comments: Standard CO2 deployment.		

Buoy Site: 2N 155W				
Mooring Operation: Recovery	Mooring ID#: DM057A			
Deployed Location: 01 59.25N 154 57.83W	Deployed Date: 09/29/13			
Recovered Location: 01 59.0N 154 55.8W	Recovered Date: 11/18/14			
Sensors/Equipment Lost at Sea: None				
Sensors Damaged/Fouled: T25 slid to 50m, T50 slid to 75m; Anemometer stanchion bent 45°				

Fishing/Vandalism: None					
Sensors/Tubes Downle	oaded: None				
General Comments: 3	Standard deployment				
Site Sensor Failures	Date Data Flagged Why Data Flagged Field Service				
			Observations		
T50	8/23/14	Data failed	Mount slid		
Wind	7/25/14	WSPD too low	Stanchion bent		
T25	3/2/14 Data failed Mount slid				
ATMP/RH	10/7/13	High/erratic	None		

Buoy Site: 2N 155W	Mooring Depth: 4662m		
Mooring Operation: Deployment	Mooring ID#: DM111A		
Deployed Location: 01 59.08N 154 58.38W Deployed Date: 11/19/2014			
Pre-Deployment On Deck Instrument Failures: None			
Sensors/Equipment Lost at Sea: None			
Sensors Damaged During Deployment: None			
General Comments: Standard deployment with fairings			

Buoy Site: 5N 155W					
Mooring Operation:	Mooring Operation: Recovery Mooring ID#: DM062A		062A		
Deployed Location: 0	5 00.3N 154 57.0W	Deployed Date: 10	0/08/13		
Recovered Location:	04 59.2N 154 57.2W	Recovered Date: 1	1/19/14		
Sensors/Equipment L	ost at Sea: None	<u> </u>			
Sensors Damaged/Fou	iled: SSC unplugged, T	25 slid to 50m, T200 sli	d to 250m		
Fishing/Vandalism:	None				
Sensors/Tubes Downl	oaded: None				
General Comments:	Standard recovery				
Site Sensor Failures	Date Data Flagged	Why Data Flagged	Field Service		
	Observations				
SST/SSS	S 2/8/14 Data missing Fouled/Damaged,				
	cable unplugged, 2				
	pins missing				
RH	1/2/14	Data too high None			
T50	10/15/13	Data missing	No comms		

Buoy Site: 5N 155W	Mooring Depth: 4582m			
Mooring Operation: Deployment	Mooring ID#: DM112A			
Deployed Location: 05 00.1N 154 57.1W	Deployed Date: 11/20/2014			
Pre-Deployment On Deck Instrument Failures: None				
Sensors/Equipment Lost at Sea: None				

Sensors Damaged During Deployment: None
General Comments: Standard deployment

Buoy Site: 8N 155W				
Mooring Operation:	Mooring Operation: Recovery Mooring ID#: DM056A			
Deployed Location: 0	Deployed Location: 08 00.5N 154 57.0W Deployed Date: 09/26/13		0/26/13	
Recovered Location:	07 59.17N 154 59.35W	Recovered Date: 1	1/20/14	
Sensors/Equipment L	ost at Sea: None			
Sensors Damaged/Fou	iled: None			
Fishing/Vandalism: None				
Sensors/Tubes Downloaded: None				
General Comments: Standard deployment				
Site Sensor Failures Date Data Flagged Why Data Flagged Field Service				
Observations				
RH	6/29/14	Data too high	None	
T25-TP500	6/16/14	Data missing	None	

Buoy Site: 8N 155W	Mooring Depth: 5225m		
Mooring Operation: Deployment	Mooring ID#: DM113A		
Deployed Location: 07 57.04N 154 59.37W	Deployed Date: 11/21/2014		
Pre-Deployment On Deck Instrument Failures: None			
Sensors/Equipment Lost at Sea: None			
Sensors Damaged During Deployment: None			
General Comments: Standard deployment			

2.2 <u>CTD Casts Completed</u>

A Sea-Bird 911plus CTD with dual temperature and conductivity sensors was provided by the NMAO. Temperature and conductivity sensors are calibrated yearly at Sea-Bird and sent in for diagnostics as necessary.

The following outlines the CTD casts completed during the cruise:

CTD Operations				
Coordinates	Comments			
08 17.2395S 155 01.2592W	11/14/14	RB060011		
06 59.8702S 155 00.4577W	11/14/14	RB060021		
05 59.9478S 154 59.7893W	11/14/14	RB060031		
04 59.5392S 155 00.0361W	11/16/14	RB060041		

00 50 06650 155 00 000000	11/12/11	DD060051	
03 59.9665S 155 20.2773W	11/16/14	RB060051	
03 00.0353S 155 09.7883W	11/16/14	RB060061	
01 59.0702S 154 59.7188W	11/17/14	RB060071	
00 59.8602S 154 57.4334W	11/17/14	RB060081	
00 01.2003S 154 54.8633W	11/18/14	RB060091	
00 59.9621N 154 57.0388W	11/18/14	RB060101	
01 58.6459N 154 57.3745W	11/19/14	RB060111	
03 00.0332N 154 57.2382W	11/19/14	RB060121	
04 00.0421N 154 56.5554W	11/19/14	RB060131	
04 59.6454N 154 56.3555W	11/20/14	RB060141	
06 00.1572N 154 58.7889W	11/20/14	RB060151	
07 00.1415N 155 00.1003W	11/20/14	RB060161	
07 56.6156N 154 57.9214W	11/21/14	RB060171	

2.3 Ancillary Science Projects Completed on the Cruise

The following outlines the ancillary science work performed in conjunction with the TAO operations on the cruise:

Pacific Marine Environmental Laboratory (PMEL) Argo Profiling CTD Floats

Seven (7) Argo floats were scheduled for deployment on this cruise. The chief scientist verified and briefed the Operations Officer on the deployment positions prior to the start of the cruise. All Argo Float deployments were completed as scheduled.

Questions concerning ARGO Floats should be directed to:

Gregory Johnson, NOAA/PMEL or Elizabeth Steffen, NOAA/PMEL

Tel: (206) 526-6806 Tel: (206) 526-6747

E-mail: pmel_floats@noaa.gov E-mail: pmel_floats@noaa.gov

The following outlines the Argo floats deployed during the cruise:

ARGO Floats				
Coordinates	Date	SN#	Comments	
01 03.8720N 178 59.1121E	11/7/2014	214		
00 56.3185S 178 45.0768W	11/8/2014	405		
04 57.7544S 155 00.2650W	11/16/2014	224		
01 57.7547S 155 00.4270W	11/17/2014	404		
00 00.3949N 154 55.4660W	11/18/2014	406		
01 59.1667N 154 58.7319W	11/19/2014	407		
05 00.4669N 154 57.7729W	11/20/2014	408		

Atlantic Oceanographic and Meteorological Laboratory (AMOL) Surface Drifting Floats

Ten (10) AOML Surface Drifters were scheduled for deployment on this cruise. The chief scientist verified and briefed the Operations Officer on the deployment positions prior to the start of the cruise. All AOML Surface Drifter deployments were completed as scheduled.

Questions concerning AOML Surface Drifters should be directed to:

Shaun Dolk, NOAA/AOML Global Drifter Center,

Tel: (305) 361-4546 Fax: (305) 361-4436

E-mail: shaun.dolk@noaa.gov

The following outlines the AOML Drifting floats deployed during this cruise:

AOML Floats				
Coordinates	Date	SN#	Comments	
04 57.6802S 155 00.2729W	11/16/2014	127114		
04 57.6802S 155 00.2729W	11/16/2014	127115		
04 57.6802S 155 00.2729W	11/16/2014	127107		
04 57.6802S 155 00.2729W	11/16/2014	127106		
01 57.7427S 155 00.4258W	11/17/2014	127103		
01 57.7427S 155 00.4258W	11/17/2014	127105		
00 00.4011N 154 55.4662W	11/18/2014	116437		
00 00.4011N 154 55.4662W	11/18/2014	127104		
01 59.1642N 154 58.7314W	11/19/2014	116435		
05 00.4794N 154 57.7668W	11/20/2014	116436		